

Water Testing Results - Morrison Alternative School

Action Level is 15 parts per billion (ppb)

Fixture Location/Description	Fixture ID #	Test Date	Test Result
Hallway Drinking Fountain #1 (chilled)	21900600-001DW	4/10/23	ND
Hallway Drinking Fountain #2 (chilled)	21900600-002DW	4/10/23	ND
Water Bottle Refill (chilled)	21900600-003WB	4/10/23	ND
Rm. 1 Sink Faucet	21900600-004CF	Fixture N/A	-
Rm. 1 Drinking Fountain	21900600-005DW	Fixture N/A	-
Rm. 2 Sink Faucet	21900600-006CF	4/10/23	ND
Walker Rm. Sink Faucet	21900600-007CF	4/10/23	3.77
Walker Rm. Restroom Sink Faucet	21900600-008BF	4/10/23	ND
Rm. 3 Sink Faucet	21900600-009CF	4/10/23	3.25
Rm. 3 Drink Fountain	21900600-010DW	Fixture N/A	-
Hallway Drink Fountain #3 (chilled)	21900600-011DW	4/10/23	ND
Hallway Drink Fountain #4 (chilled)	21900600-012DW	4/10/23	12
Water Bottle Refill (chilled)	21900600-013WB	4/10/23	ND
Rm. 4 Sink Faucet	21900600-014CF	4/10/23	9.88
Rm. 4 Drink Fountain	21900600-015DW	4/10/23	2.17
Rm. 5 Sink Faucet	21900600-016CF	4/10/23	ND
Rm. 5 Drink Fountain	21900600-017DW	4/10/23	6.22
Rm. 6 Sink Faucet	21900600-018CF	4/10/23	ND
Rm. 6 Drink Fountain	21900600-019DW	4/10/23	2.82
Rm. 7 Sink Faucet	21900600-020CF	4/10/23	4.81
Girl's Restroom Sink Faucet	21900600-021BF	4/10/23	5.54
Girl's Restroom Sink Faucet	21900600-022BF	4/10/23	5.33
Custodial Closet Sink Faucet	21900600-023SF	4/10/23	10.22
Boy's Restroom Sink Faucet	21900600-024BF	4/10/23	5.51
Boy's Restroom Sink Faucet	21900600-025BF	4/10/23	9.4
Boy's Restroom Sink Faucet	21900600-026BF	4/10/23	1.43
Rm. 1 Sink Faucet	21900600-027CF	Previous Retest	N/A
	21900600-028DW	Previous Retest	N/A

Any fixture testing at or above the action level of 15 ppb is immediately removed from service and cannot be returned to service until it has been remediated and passed follow-up testing

RETESTS			

ND = Non Detect - Lead level is below the set detection limits of **1** ppb