

Water Testing Results - District Office

Action Level is 15 parts per billion (ppb)

Fixture Location/Description	Fixture ID #	Test Date
Rm. 170 Sink Faucet	21900000-001CF	4/10/23
Staff Lounge Sink Faucet	21900000-002SF	4/10/23
Staff Lounge Ice Maker	21900000-003IM	4/10/23
Men's Restroom Sink Faucet	21900000-004BF	4/10/23
Men's Restroom Sink Faucet	21900000-005BF	4/10/23
Men's Restroom Sink Faucet	21900000-006BF	4/10/23
Custodian's Office Women's Restroom Sink Faucet	21900000-007BF	4/10/23
Custodian's Office Women's Restroom Sink Faucet	21900000-008BF	4/10/23
Women's Restroom Sink Faucet	21900000-009BF	4/10/23
Women's Restroom Sink Faucet	21900000-010BF	4/10/23
Hallway Drink Fountain #1	21900000-011DW	4/10/23
Rm. 170 Sink Faucet	21900000-012CF	previous retest
Men's Restroom Sink Faucet	21900000-013BF	5/2/23

Any fixture testing at or above the action level of 15 ppb is immediately removed from service and cannot be returned to service until it has been remediated and passed follow-up testing

RETESTS		
Men's Restroom Sink Faucet - Retest for 006BF	21900000-013BF	5/2/23

ND = Non Detect - Lead level is below the set detection li of **1** ppb



Test Result

2.14

6.23

ND

ND

ND

49.8

10.2

ND

ND

2.11

4.03

14.3



14.3

